Strawn, William (DBI)

From:

Clancy, Fergal (DBI)

Sent:

Friday, September 07, 2018 4:51 PM

To:

Strawn, William (DBI); O'Riordan, Patrick (DBI)

Cc:

Hui, Tom (DBI); Jayin, Carolyn (DBI); Madjus, Lily (DBI); Clancy, Fergal (DBI); Sweeney,

Edward (DBI); Ho, Gary (DBI); Lowrey, Daniel (DBI); Yu, Cyril (DBI)

Subject:

FW: 301 Mission Street, 36B / Response to Correction Notice

Attachments:

Ltr to DBI in Response to Correction Notice re 36B (9-7-2018).pdf

Bill/ Pat

Please see attached report to address the correction notice, and advise any follow up

Fergal Clancy

Building Inspector Department of Building Inspection San Francisco, CA 94103-2414 1 (415) 575 6920

fergal.clancy@sfgov.org

From: Linda Hughes [mailto:linda@constructiondefects.com]

Sent: Friday, September 07, 2018 4:27 PM

To: Clancy, Fergal (DBI) <fergal.clancy@sfgov.org>; O'Riordan, Patrick (DBI) <patrick.oriordan@sfgov.org> Cc: Tom Miller <tmiller@constructiondefects.com>; Rachel Miller <rachel@constructiondefects.com>; Scott Tate <state@constructiondefects.com>; John Bauman <jbauman@constructiondefects.com>; Steven Lovazzano <slovazzano@constructiondefects.com>

Subject: 301 Mission Street, 36B / Response to Correction Notice

Dear Messrs. Clancy & O'Riordan,

Please see attached correspondence from Tom Miller, Esq. on behalf of The Millennium Tower Association regarding the Correction Notice dated September 4, 2018.

Thank you, Linda Hughes

Assistant to Thomas E. Miller

Linda Hughes | Senior Case Manager | E: linda@constructiondefects.com | 235 Montgomery St., Suite 930, San Francisco, CA, 94104 | P: 415.437.1800 | F: 415.437.0177 | 5201 Great America Parkway, Suite 320, Santa Clara, CA 95054 | P: 408.275.9094 | 19 Corporate Plaza Drive, Newport Beach, CA, 92660 | P: 949.252.9150 | F: 949.442.0646 | www.constructiondefects.com | The Miller Law Firm | Celebrating 40 Years





September 7, 2018

San Francisco 235 Montgomery Street Suite 930 San Francisco, CA 94104 (415) 437-1800

www.constructiondefects.com

Via Email

City and County of San Francisco Department of Building Inspection

Attn: Fergal Clancy

Patrick O'Riordan

Re: 301 Mission Street, 36B

Response to Correction Notice and Report dated September 4, 2018

Dear Messrs. Clancy & O'Riordan:

We represent The Millennium Tower Association and are providing this response to the Correction Notice and Report referenced and attached.

Enclosed please find a letter report of this same date from Allana Buick & Bers addressing the requested information.

If there is any further information needed, please contact us.

Very truly yours,

THE MILLER LAW FIRM

Thomas E. Miller

TEM:lh Enclosure Sept 4th 2018

CITY AND COUNTY OF SAN FRANCISCO

DEPARTMENT OF BUILDING INSPECTION

Santano

CORRECTION NOTICE

301 Mission Freet 36 B.

This in Response to the cracked glazzing on the exhibit poinel in unit 36 B.

erounder a Report and evaluation on the extent of the Rapairs

This Report will tracebe the Condition of the Adsorant Curtain vall System and to be Provided within 72 his close of Duniess truly 9-7-18

SIO & Chances

415 575 6926

9-4-18



Allana Bulck & Bors, Inc. 90 Commercial Street Palo Alto, CA 94303 f 650.543.5625

ALLANA BUICK & BERS

September 7, 2018

Mr. Tom Miller The Miller Law Firm 235 Montgomery St. Suite 930 San Francisco, CA 94104

Re:

The Millennium Tower **Unit 36B Cracked Glass**

Dear Mr. Miller,

At the request of the Millennium Tower Association (MTA), Allana Buick and Bers (ABBAE) has performed a preliminary evaluation of the cracked glass in unit 36B of the Millennium Tower. Thus far, we have only had access to the interior of the building unit, as the house swing stage is broken. In order to perform an evaluation as to why the glass has cracked, a hands-on exterior examination is required to measure the curtain wall frames and to see why the lite was stressed.

The existing curtain wall system is designed to allow for building deflection due to wind loads and seismic forces, without causing glass failure. The fact that this piece of glass may have failed due to the building tilt may be a localized defect or potentially be more widespread. Further, investigation of the building exterior is required to understand and assess the issue.

As the house swing stage is in the process of being repaired, the team has secured other options for exterior observations such as drone photography and high-powered telephoto lens photography from adjacent buildings tomorrow. We are also arranging for an individual to rappel down the building early next week to photograph the curtain wall and glass, and tape up the glass from the exterior to make it safe. Once the house swing stage is repaired, our technical staff will access the glass from the exterior and conduct a forensic evaluation before ordering a replacement glass.

ABBAE has taken the lead on coordinating repair options for the cracked glass. Ultimately, the repair is to replace the affected glass with a new piece of glass, matching the existing specifications. The process of determining the specifications for replacement and ordering new glass is ongoing. Lead time for a new lite is several weeks. To replace the glass, exterior access to the cracked glass is needed and can only happen once the house swing stage is operational and is re-certified for safety, which may take 2 to 3 weeks. Our investigation is ongoing and we will be at the site tomorrow to continue this work.

Sincerely,

Very truly yours,

Allana Buick & Bers, Inc.

Karim P. Allana, PE, RRC, RWC

CEO, Senior Principal