



FIRE INSPECTION REPORT - NOTICE OF FIRE CODE VIOLATION

Date of Inspection: Tue Jan 29, 2008

Time: 13:30

Inspection Type: Inspection - Public School/Fire &

BUSINESS/OPERATION

Davis Drive Elementary School
2151 DAVIS DR

Apex, NC 27502

Date of Next Reinspection: _____

THE FOLLOWING ITEMS ARE IN VIOLATION OF THE N.C. STATE FIRE PREVENTION CODE. YOU ARE REQUIRED TO CORRECT ALL ITEMS NOTED BELOW:

Code Correction to be Made

1025.1 General.

In addition to the means of egress required by this chapter, provisions shall be made for emergency escape and rescue in Group E classrooms

EMERGENCY WINDOW OBSTRUCTED:

- ****1) 214
- ****2) 304
- ****3) 309

1025.1 General.

In addition to the means of egress required by this chapter, provisions shall be made for emergency escape and rescue in Group E classrooms

ROOMS NOT DESIGNED FOR CLASSROOM USE

ROOMS-STORAGE AND OFFICE

NO SECONDARY MEANS OF EGRESS

- ****1) 100-L WINDOW NOT OPERABLE AND HEIGHT OF WINDOW
- ****2) 113 - TEACHER OFFICE
- ****3) 215-A WINDOW HEIGHT

1027.2 Reliability.

Required exit accesses, exits or exit discharges shall be continuously maintained free from obstructions or impediments to full instant use in the case of fire or other emergency when the areas served by such exits are occupied. Security devices affecting means of egress shall be subject to approval of the fire code official.

- ****1) TABLE AND CHAIRS IN EXITWAY TO DOOR : 217
- ****2) STORAGE IN CORRIDOR ; NEAR 408

315.2.1 Ceiling clearance.

Storage shall be maintained 2 feet or more below the ceiling in nonsprinklered areas of buildings or a minimum of 18 inches below sprinkler head deflectors in sprinklered areas of buildings.

MAINTAIN CLEARANCE FROM CEILING FOR STORED ITEMS:

- ****1) 101-C
- ****2) 221
- ****3) 309