



FIRE INSPECTION REPORT - NOTICE OF FIRE CODE VIOLATION

Date of Inspection: Wed May 21, 2008 Time: 13:00
 Inspection Type: Inspection - Public School/Fire &

BUSINESS/OPERATION

Weatherstone Elementary School
 1000 OLDE WEATHERSTONE WY

 Cary, NC 27513

Date of Next Reinspection: _____

THE FOLLOWING ITEMS ARE IN VIOLATION OF THE N.C. STATE FIRE PREVENTION CODE. YOU ARE REQUIRED TO CORRECT ALL ITEMS NOTED BELOW:

Code	Correction to be Made
1006.3	Illumination emergency power. The power supply for means of egress illumination shall normally be provided by the premises electrical supply. In the event of power supply failure, an emergency electrical system shall automatically illuminate EMERGENCY LIGHTS: NOT WORKING : ****1) ABOVE CAFETERIA KITCHEN SINK: 177
1025.1	General. In addition to the means of egress required by this chapter, provisions shall be made for emergency escape and rescue in Group E classrooms, ****1) EMERGENCY WINDOW OBSTRUCTED : 403
1027.2	Reliability. Required exit accesses, exits or exit discharges shall be continuously maintained free from obstructions or impediments to full instant use in the case of fire or other emergency when the areas served by such exits are occupied. Security devices affecting means of egress shall be subject to approval of the fire code official. ****1) CORRIDOR CAN NOT BE USED FOR A CLASSROOM : NEAR 164 SIDE EXITWAY OBSTRUCTED BY TABLES, CHAIRS ****2) DESK AND TABLE IN EXTERIOR EXITWAY DOOR : 204 MOVE DESK AND TABLE IN FRONT OF DOOR
1027.2	Reliability. Violation carried over from inspection on 12/17/2007 Required exit accesses, exits or exit discharges shall be continuously maintained free from obstructions or impediments to full instant use in the case of fire or other emergency when the areas served by such exits are occupied. Security devices affecting means of egress shall be subject to approval of the fire code official. ****1) CORRIDOR CAN NOT BE USED FOR A CLASSROOM : NEAR 164 /// AS OF 05/21/08 THE ABOVE VIOLATION-NOT CORRECTED
1204.2.1	Ventilation. Ventilation shall be provided in accordance with Section 502 of the International Mechanical Code and DOL 29 CFR Part 1910.1000, where applicable. ****1) MECHANICAL WALL VENT : NOT WORKING : KILN ROOM