



**FIRE INSPECTION REPORT - NOTICE OF FIRE CODE VIOLATION**

Date of Inspection: Tue Jun 24, 2008 Time: 10:30  
Inspection Type: Inspection - Public School/Fire &

<b>BUSINESS/OPERATION</b>
Lufkin Road Middle School (yr/rd) 1002 LUFKIN RD  Apex, NC 27502

Date of Next Reinspection: \_\_\_\_\_

THE FOLLOWING ITEMS ARE IN VIOLATION OF THE N.C. STATE FIRE PREVENTION CODE. YOU ARE REQUIRED TO CORRECT ALL ITEMS NOTED BELOW:

**Code Correction to be Made**

**1006.3 Illumination emergency power.**

The power supply for means of egress illumination shall normally be provided by the premises electrical supply. In the event of power supply failure, an emergency electrical system shall automatically illuminate

EMERGENCY LIGHTS: NOT WORKING :

- \*\*\*\*1) M-2
- \*\*\*\*2) M-3
- \*\*\*\*3) 300
- \*\*\*\*4) 304-A

**1011.2 Reliability.**

Violation carried over from inspection on 12/05/2007  
Violation carried over from inspection on 03/15/2007  
Violation carried over from inspection on 09/18/2006

Required exit accesses, exits or exit discharges shall be continuously maintained free from obstructions or impediments to full instant use in the case of fire or other emergency.

\*\*\*\*1) CLEAR ITEMS IN CORRIDOR : EXIT GYM TO REAR EXIT : NEAR E-2

////////////////////////////////////

AS OF 06/24/08 THE ABOVE VIOLATION -NOT CORRECTED

**1011.2 Reliability.**

Violation carried over from inspection on 12/05/2007  
Violation carried over from inspection on 03/15/2007  
Violation carried over from inspection on 03/22/2005

Required exit accesses, exits or exit discharges shall be continuously maintained free from obstructions or impediments to full instant use in the case of fire or other emergency.

\*\*\*\*1) CLEAR CORRIDOR FROM GYM TO BACK EXIT:

VIOLATION REPORTED : 7/27/99

- 1/13.00
- 1/16/01
- 8/29/01
- 9/27/02
- 3/10/04

////////////////////////////////////

AS OF 06/24/08 THE ABOVE VIOLATION-NOT CORRECTED